



Обозначение	L	L1	L2	L3	L4	L5	L6
UW-PR1.00.08	520	200	142	164	191	233	256
01-600-000	600	200	410	164	191	233	256

1. *Размеры для справок.
2. H12;h12;+IT12/2.

[illegible]